

# **Six Mile Lake Shoreline Survey 2016**

*By Tip of the Mitt Watershed Council*

Report written by:

**Matt L. Claucherty**

*Monitoring and Research Coordinator*

## Table of Contents

	Page
<b>List of Tables and Figures</b> .....	<b>iii</b>
<b>Summary</b> .....	<b>2</b>
<b>Introduction</b> .....	<b>3</b>
Background.....	4
Shoreline Development Impacts.....	4
Study Area.....	8
<b>Methods</b> .....	<b>13</b>
Field Survey Parameters.....	13
Data Processing.....	16
<b>Results</b> .....	<b>17</b>
<b>Discussion</b> .....	<b>23</b>
Recommendations.....	27
<b>Literature and Data Referenced</b> .....	<b>29</b>

## List of Tables

	<b>Page</b>
Table 1. Six Mile Lake Watershed land-cover statistics.....	10
Table 2. Six Mile Lake average water quality values.....	10
Table 3. Categorization system for <i>Cladophora</i> density.....	14
Table 4. <i>Cladophora</i> density results.....	17
Table 5. Greenbelt rating results.....	19
Table 6. Shoreline alteration results.....	21
Table 7. Shoreline erosion results.....	21
Table 8. Critical shoreline survey parameter comparisons: 2000 to 2016.....	24
Table 9. Shore survey statistics from Northern Michigan lakes.....	25

## List of Figures

	<b>Page</b>
Figure 1. Map of Six Mile Lake and Watershed.....	9
Figure 2. Chart of average Secchi depths in Six Mile Lake.....	11
Figure 3. Chart of chlorophyll-a concentrations in Six Mile Lake.....	12
Figure 4. <i>Cladophora</i> algae density results for Six Mile Lake.....	18
Figure 5. Greenbelt score totals results for Six Mile Lake.....	20
Figure 6. Shoreline erosion severity results for Six Mile Lake.....	22

## SUMMARY

During the early summer of 2016, the Tip of the Mitt Watershed Council conducted a shoreline survey of Six Mile Lake as part of a comprehensive shoreline survey for the entire Elk River Chain of Lakes. Watershed Council staff and interns surveyed the upper Elk River Chain (Beals Lake through Intermediate Lake) in 2016 and the lower Elk River Chain (Lake Bellaire through Elk Lake) in 2017. Surveys were designed to document conditions that can potentially impact water quality, including the three biggest threats to inland lakes: nutrient pollution, habitat loss, and shoreline erosion.

Survey results indicate that human activity along the Six Mile Lake shoreline is likely impacting the lake ecosystem and water quality. Nearly half (41%) of all shoreline properties had little to no vegetation growing at water's edge. This figure is steadily increasing, from 23% in 2000 and 34% in 2008. Vegetation removal is concentrated along the western shoreline, and near the center of the lake on the eastern shoreline. Erosion and shoreline alterations have also increased over the past 16 years, and exhibit similar spatial patterns as vegetation removal.

On a positive note, the number of properties showing signs of nutrient pollution has decreased, relative to previous surveys. *Cladophora*, an algal indicator of nutrient pollution, was documented at 10% of all properties, down from 14% in 2008.

Steps can be taken to improve the habitat and water quality of Six Mile Lake. Erosion sites can be repaired, vegetation can be allowed to regrow on the shoreline, providing improved pollutant filtration and erosion resistance. Outreach to shoreline property owners regarding lake-friendly shoreline management practices can help to improve conditions. Educating residents on beneficial and harmful activities is often all that is needed to bring about change.

## INTRODUCTION

### **Background:**

During the late spring of 2016, a shoreline survey was conducted on Six Mile Lake by the Tip of the Mitt Watershed Council (Watershed Council) to document shoreline conditions that potentially impact water quality. The entire shoreline was surveyed to document the following: algae as a nutrient pollution indicator, erosion, shoreline alterations, greenbelts, and tributary inlets and outlets. This survey was funded by a grant from the Michigan Department of Environmental Quality as part of a larger Elk River Watershed protection initiative.

Over the past two decades, four shoreline surveys have been conducted on Six Mile Lake. In 1993, the Six Mile Lake Association contracted with the Tip of the Mitt Watershed Council to conduct a survey using a conductivity meter to detect locations of septic system problems. A database of shoreline property features and ownership information, and parcel maps were also developed during that survey. The project included a questionnaire mailing to shoreline property owners, an individualized response with recommendations, and ground water testing at 14 suspected problem sites. From 1996 to 1998, another survey was conducted as part of the State and Federally-funded Elk River Chain of Lakes Watershed Project. That survey documented occurrences of filamentous algae growth and shoreline erosion problems, as well as other resource features such as wetlands, aquatic plant beds, and bottom sediments. The shoreline database and parcel maps were updated at that time. There were no individualized follow-up activities. In 2000, a third survey was performed to document nutrient pollution (using both algae and conductivity) and greenbelt status, but there were no individualized follow-up activities. A 2008 survey was sponsored by the Six Mile Lake Association. The methods used in the 2008 survey were very similar to those employed in the 2016 survey. Algal signs of nutrient pollution, erosion, and greenbelt status were all quantified.

The 2016 survey provides a comprehensive data set documenting shoreline conditions on Six Mile Lake; a valuable data set that can be used as a lake management tool. Combined with

follow-up activities, such as questionnaires and on-site visits, problems in shoreline areas that threaten the lake's water quality can be identified and corrected. These solutions are often simple and low cost, such as regular septic system maintenance, proper lawn care practices, and wise land use along the shoreline. Prevention of problem situations can also be achieved through the publicity and education associated with the survey. Periodic repetition of shoreline surveys is important for identifying new and chronic problem sites, determining long-term trends of near-shore nutrient inputs and shoreline alterations associated with land-use changes, and for assessing the success of remedial actions.

### **Shoreline Development Impacts:**

Lake shorelines are the critical interface between land and water, where human activity has the greatest potential for degrading water quality. Traditional development of shoreline properties for residential, commercial, or other uses invariably leads to negative impacts on the lake ecosystem. During the development process, the natural landscape is altered in a variety of ways: vegetation is removed, the terrain is graded, utilities are installed, structures are built, and areas are paved. These changes to the landscape and subsequent human activity in the shoreline area have consequences on the aquatic ecosystem. Nutrients from organic wastes, contaminants from cars and roads, and soils from eroded areas are among some of the pollutants that end up in and negatively impact the lake following shoreline development.

Nutrient pollution can have adverse impacts on aquatic ecosystems and pose a danger to human health. While nutrients are necessary to sustain a healthy aquatic ecosystem, excess nutrients will stimulate nuisance aquatic plant growth of both macrophytes (aquatic plants that grow in or near water and are either emergent, submergent, or floating) and algae.

Additionally, algal blooms pose a public health risk as some species (i.e. blue green algae) produce toxins, including hepatotoxins (toxins that cause liver damage) and neurotoxins (toxins that affect the nervous system). Excess plant and algae growth can also degrade water quality by depleting the ecosystem's dissolved oxygen stores. During nighttime respiration, plants compete with other organisms for a limited oxygen supply. Furthermore, the decomposition of

algae and plants has the potential to deplete dissolved oxygen supplies due to the aerobic activity of decomposers, particularly in the deeper waters of stratified lakes.

In general, small and shallow lakes, such as Six Mile Lake, are more sensitive to nutrient pollution. Because larger lakes have a greater water volume and dissolved oxygen stores, they tend to be less susceptible to nutrient pollution. By contrast, small lakes generally have smaller stores of dissolved oxygen and a lesser ability to dilute nutrients; therefore, they are more susceptible to the indirect impacts of nutrient pollution. Nutrient pollution can be more problematic in small lakes due to extensive shallow areas that can support more aquatic plant growth.

Surface waters receive nutrients through a variety of natural and cultural (human) sources. Natural sources of nutrients include stream inflows, groundwater inputs, surface runoff, organic inputs from riparian (shoreline) areas, and atmospheric deposition. Springs and seeps, streams, and artesian wells are often naturally high in nutrients due to the geologic strata they encounter. Nearby wetland seepages may also discharge nutrients at certain times of the year. Cultural sources include septic systems, fertilizers, and stormwater runoff from roads, driveways, parking lots, roofs, and other impervious surfaces. Poor agricultural and forestry practices, which oftentimes result in soil erosion, and wetland destruction also contribute to nutrient pollution. Furthermore, some cultural sources (e.g., malfunctioning septic systems) pose a potential health risk due to bacterial and viral contamination.

Severe nutrient pollution is detectable through chemical analyses of water samples, physical water measurements, and the utilization of biological indicators (a.k.a., bio-indicators). Although chemical analyses of water samples to check for nutrient pollution can be effective, they are oftentimes more labor intensive and costlier than other methods. Typically, water samples are analyzed to determine nutrient concentrations (usually forms of phosphorus and nitrogen), but other chemical constituents, such as chloride, can be measured. Physical measurements, such as water temperature and conductivity (i.e., the water's ability to conduct

an electric current), are primarily used to detect malfunctioning septic systems. Biologically, nutrient pollution can be detected along the lake shore by noting the presence of *Cladophora* algae, a bio-indicator.

*Cladophora* is a branched, filamentous green algal species that occurs naturally in small amounts in Northern Michigan lakes. Its occurrence is governed by specific environmental requirements for temperature, substrate, nutrients, and other factors. It is found most commonly in the wave splash zone and shallow shoreline areas of lakes, as well as streams. It grows best on stable substrates such as rocks and logs, though artificial substrates such as concrete or wood seawalls are also suitable. *Cladophora* prefers water temperatures in a range of 50 to 70 degrees Fahrenheit, which means that the optimal time for its growth and detection in Northern Michigan lakes is from mid-May to early July, and September to October.

The nutrients required for *Cladophora* to achieve large, dense growths are typically greater than the nutrient availability in the lakes of Northern Michigan. Therefore, shoreline locations where relatively high concentrations of nutrients, particularly phosphorus, are entering a lake can be identified by noting the presence of *Cladophora*. Although the growth features of *Cladophora* can be influenced by factors such as current patterns, shoreline topography, substrate composition, and wave action, the presence or absence of any significant growth is a powerful lake-wide screening tool. It can reveal the existence of chronic nutrient loading problems and assess the effectiveness of any remedial actions. Comparisons of the total number of algal growths can reveal trends in nutrient inputs due to changing land use.

Erosion along the shoreline has the potential to degrade the lake's water quality. Stormwater runoff through eroded areas carries sediments into the lake and impacts the lake ecosystem in a variety of ways. Sediments clog the gills of fish, aquatic insects and other aquatic organisms. Excessive sediments smother fish spawning beds and fill interstitial spaces that provide habitat for a variety of aquatic organisms. Suspended sediments absorb sunlight energy and increase water temperatures. In addition, nutrients adhere to sediments that wash in from eroded

areas, which can lead to nuisance aquatic plant growth and algal blooms.

Shoreline greenbelts are essential for maintaining a healthy aquatic ecosystem. A greenbelt consisting of a variety of native woody and herbaceous plant species provides habitat for near-shore aquatic organisms as well as other shoreline-dependent wildlife. They also help to stabilize shorelines against wave and ice action with their extensive network of deep, fibrous roots. Greenbelts also provide shade to nearshore areas, which is particularly important for lakes with cold water fisheries. In addition, greenbelts provide a mechanism to filter pollutants carried by stormwater from rain events and snowmelt.

Tributaries have a significant potential for influencing a lake's water quality as they are one of the primary conduits through which water is delivered to a lake from its watershed. Inlet streams may provide exceptionally high quality waters that benefit the lake ecosystem; conversely, they have the potential to deliver polluted waters that degrade the lake's water quality. Outlet streams flush water out of the lake, providing the means to remove contaminants that have accumulated in the lake ecosystem. With regard to shore surveys, noting the location of inlet tributaries is very helpful when evaluating shoreline algae conditions because nutrient concentrations are generally higher in streams than in lakes. The relatively higher nutrient levels delivered from streams often lead to naturally heavier *Cladophora* and other algal growth in nearby shoreline areas.

Lake-friendly shoreline property management is paramount for protecting water quality and sustaining a healthy, thriving lake ecosystem. Septic system maintenance, stormwater management, erosion control, and the elimination of fertilizers, herbicides, and pesticides are among the many low-cost best management practices that minimize the impact of shoreline properties on water quality.

**Study Area:**

Six Mile Lake is located in Antrim County (Echo Township) and Charlevoix County (South Arm Township) of the northwest Lower Peninsula of Michigan. Based upon shoreline digitizing using 2005 aerial photographs, the surface area of Six Mile Lake is approximately 350 acres and the shoreline distance totals ~9 miles (Figure 1). The deepest point is located near the center of the lake and is reported to be from 30-32' deep.

Six Mile Lake is a glacially formed lake that is located near the headwaters of the Elk River Chain of Lakes. There are numerous inlet streams; the largest being the Dingman River at the southern end, which drains Scotts and Beals Lakes to the south. The next largest inlet streams include Vance Creek in the southeast and Liscon Creek in the northeast. The only outlet is located in the northern end, which carries water to St. Clair Lake and down through the rest of the chain.

The Six Mile Lake watershed is a sub-watershed of the Elk River watershed, which is, in turn, part of the larger Grand Traverse Bay Watershed. Six Mile Lake has a large watershed in relation to the lake's surface area, measuring approximately 22,452 acres (does not include lake area). The watershed area to lake surface area ratio is ~64:1, which, compared to other lakes in Michigan, is quite high (e.g., Walloon Lake has a ratio of ~5:1). This ratio provides a statistic for gauging susceptibility of lake water quality to changes in watershed land cover. Essentially, the statistic indicates that the Six Mile Lake watershed is large enough, relative to lake area, to provide a protective buffer, such that small areas of development will probably not negatively impact water quality. However, the cumulative impact of rampant landscape development throughout the watershed could have serious adverse impacts on the lake's water quality.

According to land cover statistics from a 2000 land cover analysis (NOAA, 2003), the majority of the watershed is forested. Of land cover types that typically contribute to water quality degradation, there is little urban/residential and a moderate amount of agriculture in the watershed (Table 1).




Figure 1. Map of Six Mile Lake and its Watershed.

**Table 1.** Six Mile Lake watershed land cover, 2000.

<b>Land Cover Type</b>	<b>Acres</b>	<b>Percent</b>
Agriculture	3320.53	14.55
Barren	20.53	0.09
Forested	12924.87	56.64
Grassland	2284.42	10.01
Scrub/Shrub	448.38	1.96
Urban/residential	359.92	1.58
Wetland	2979.20	13.05
Water	483.17	2.12
TOTAL	22821.03	100.00

According to data collected in programs coordinated by the Tip of the Mitt Watershed Council, Six Mile Lake contains high quality waters that are typical for the region. As part of the Watershed Council’s Comprehensive Water Quality Monitoring Program (CWQM), numerous parameters have been monitored in Six Mile Lake on a triennial basis since 1995. Dissolved oxygen concentrations have typically exceeded standards established by the State of Michigan and pH has consistently complied with State standards (Table 2). Chloride levels have increased gradually over time, indicating that there are some impacts from urbanization and residential development. Typical of high-quality lakes in northern Michigan, nutrient concentrations on Six Mile Lake have been quite low (total phosphorus, nitrate and total nitrogen), with phosphorus levels decreasing through time. Based on the Redfield Ratio of 16:1 (nitrogen: phosphorus), the limiting nutrient in Six Mile Lake is phosphorus, which means that phosphorus is the nutrient in smallest supply and which would stimulate the most plant growth.


**Table 2.** Six Mile Lake data from the CWQM program.

	<b>DO</b>	<b>pH</b>	<b>Conductivity</b>	<b>Chloride</b>	<b>Nitrate</b>	<b>TN</b>	<b>TP</b>
Units	PPM	Units	microSiemens	PPM	PPB	PPB	PPB
Average	10.17	7.99	298.21	5.94	226	486	9.08
Minimum	3.22	7.30	259.10	4.00	120	323	0.80
Maximum	11.90	8.51	357.00	8.90	306	767	34.2


\*DO = dissolved oxygen, TN = total nitrogen, TP = total phosphorus, PPM = parts per million, PPB=parts per billion.

Based on data collected as part of the Watershed Council’s Volunteer Lake Monitoring Program, Six Mile Lake is classified as a mesotrophic lake (trophic status index values have ranged from 39 to 48). Mesotrophic lakes are in the middle of the road in terms of biological productivity; somewhere between the nutrient poor large, deep lakes with lackluster fisheries and the overly productive small, shallow lakes with excessive algae and plant growth. Phosphorus data from the CWQM program supports this characterization as averaged concentrations have typically been higher than large, deep lakes in the area. However, chlorophyll-a concentrations and Secchi disc depths in Six Mile Lake have decreased in recent years, which is somewhat unusual as generally one parameter increases as the other decreases (Figures 2 and 3). Invasive zebra mussels, which are now found in Six Mile Lake, usually cause increased water clarity and reduced algal biomass (i.e., reduced chlorophyll-a) by filter feeding on planktonic algae. Zebra mussels provide an explanation for the increase in water clarity seen in the Secchi disc depth data between the years of 2000 and 2005, with decreases in chlorophyll-a delayed by roughly seven years, occurring between 2007 and 2012.

**Figure 2.** Chart of average Secchi disc depths in Six Mile Lake.



**Figure 3.** Chart of average chlorophyll-a concentrations in Six Mile Lake.



## METHODS

The Six Mile Lake shoreline was comprehensively surveyed in early June of 2016 to document shoreline conditions that can potentially impact water quality. Shoreline conditions were surveyed by traveling in kayak as close to the shoreline as possible (usually within 20 feet) and noting *Cladophora* growth, substrate type, erosion, greenbelt health, shoreline alterations, and tributaries. A GPS camera was used to photograph all shoreline properties. Information for each property was recorded on field data sheets, subsequently inputted into a database, and used in conjunction with GPS data to link field data and photographs with property owner data from county equalization records.

### Field Survey Parameters

Shoreline property features were documented by photographing and noting physical features on a data sheet, such as building descriptions, public access sites, and county road endings. Due to data sheet space limits, building descriptions were recorded in an abbreviated style. For example, *Red 2 sty, brn rf, wht trm, fldstn chim, lg pine* means that the property has a red two-story house with a brown roof, white trim, fieldstone chimney, and a large pine tree in the yard. Whenever possible, names of property owners and addresses were included.

Developed parcels were noted on field data sheets and included as a separate column in the database. Properties described as developed indicate the presence of buildings or other significant permanent structures, including roadways, boat launching sites, and recreational properties (such as parks with pavilions and parking lots). Properties with only mowed or cleared areas, seasonal structures (such as docks or travel trailers), or unpaved pathways were not considered developed. Additionally, large parcels that had structures in an area far from the water's edge were not considered developed. The length and area of developed versus undeveloped shoreline was not calculated.

Many species of filamentous green algae are commonly found growing in the nearshore regions of lakes. Positive identification of these species usually requires the aid of a microscope.

However, *Cladophora* usually has an appearance and texture that is quite distinct to a trained surveyor, and these were the sole criteria upon which identification was based. Other species of filamentous green algae can respond to an external nutrient source in much the same way as *Cladophora*, though their value as an indicator species is not thought to be as reliable. When other species occurred in especially noticeable, large, dense growths, they were recorded on the data sheets and described the same as those of *Cladophora*.

When *Cladophora* was observed, it was described in terms of the length of shoreline with growth, the relative growth density, and any observed shoreline features potentially contributing to the growth. For example, “MHx30 – seeps” denotes a moderate to heavy growth that covered 30’ of the shoreline and with groundwater seeps in the area that may have been contributing to the growth. Both shoreline length and growth density are subjective estimates. Growth density is determined by estimating the percentage of substrate covered with *Cladophora* using the following categorization system:

**Table 3.** Categorization system for *Cladophora* density.

Density Category	Field Notation	Substrate Coverage
Very Light	(VL)	0% *
Light	(L)	1- 20%
Light to Moderate	(LM)	21-40%
Moderate	(M)	41-60%
Moderate to Heavy	(MH)	61-80%
Heavy	(H)	81-99%
Very Heavy	(VH)	90-100% *

*\*Very Light is noted when a green shimmer is noticed on hard substrate, but no filamentous growth present. Very Heavy overlaps with heavy and is distinguished by both high percentage of substrate coverage and long filamentous growth.*

Among other things, the distribution and size of each *Cladophora* growth is dependent on the amount of suitable substrate present. The extent of suitable substrate should therefore be

taken into account when interpreting the occurrence of individual growths, and assessing the overall distribution of *Cladophora* along a particular stretch of shoreline. Substrate types were noted during the survey, using the following abbreviations: m = soft muck or marl, s = sand, g = gravel (0.1" to 2.5" diameter), r = rock (2.5" to 10" diameter), b = boulder (>10" diameter), and w = woody debris. Substrate suitable for *Cladophora* growth include the g, r, b, and w types. The extent of suitable substrate along a shoreline parcel in terms of distance was not documented.

Erosion was noted based on shoreline areas that exhibited areas of bare soil, leaning or downed trees, exposed tree roots, undercut banks, slumping hunks of sod, or excessive deposits of sediments. Similar to *Cladophora*, shoreline erosion was recorded on field data sheets with estimates of its extent and relative severity (minor, moderate, or severe). For example "Mx20" indicated 20 feet of shoreline with moderate erosion. Additional information about the nature of the erosion, such as potential causes, was also noted.

Greenbelts (i.e., shoreline vegetation) were rated based on the length of shoreline with a greenbelt and the average depth of the greenbelt from the water's edge landward. Ratings for length ranged from 0 to 4, while ratings for depth ranged from 0 to 3. Ratings were based on the following:

**Length** ..... 0: None, 1: 1-10%, 2: 10-25%, 3: 25-75%, 4: >75%

**Depth** ..... 0: None, 1: <10 ft, 2: 10-40 ft, 3: >40 ft

Greenbelt ratings for length and depth were summed to produce an overall greenbelt score. Greenbelt scores ranged from 0 to 7, representing the greenbelt status or health. Scores of 0 were considered very poor, 1-2=poor, 3-4=moderate, 5-6=good, and 7=excellent.

Shoreline alterations were surveyed and noted with the following abbreviated descriptions: SB = steel bulkhead (i.e., seawall), BB = boulder bulkhead, CB = concrete bulkhead, RR = rock rip-rap, WB = wood bulkhead, BS = beach sand, BH = permanent boathouse, DP = discharge pipe.

Abbreviations were sometimes mixed or vary from what is listed above.

Tributaries (i.e., rivers and streams) were noted on the field data sheets and included in a separate column in the database. Additional information regarding shoreline property features or shoreline conditions recorded on field data sheets was included in the database in a “comments” column.

### **Data Processing**

Upon completing fieldwork, all field data were transferred to computer. Information from field data sheets was inputted into a Microsoft Excel® workbook. Digital photographs and GPS data were uploaded to a computer at the Watershed Council office and processed for use. Linking field and equalization data allows shoreline conditions documented during the survey to be referenced by parcel identification number or parcel owner name. Field data were linked to Antrim and Charlevoix County parcel data in a GIS with the aid of GPS and photographs. Occasionally, errors occur wherein field data are not linked to the appropriate parcel.

In order to display survey results without pinpointing specific parcels, a new map layer was developed using the parcel map data layer acquired from the county equalization departments and a Six Mile Lake shoreline layer. The new map layer consists of a narrow band following the shoreline, split into polygons that contain field and equalization data. This data layer was overlaid with other GIS data from the State of Michigan to produce a poster-size map to display survey results.

Final products include a comprehensive database, a complete set of GPS digital photographs, GIS data layers of shoreline parcels that include both county equalization and shore survey data, and a map displaying results. The database contains all data collected in the field and identification numbers in the database correspond to those in the GIS data layer and on hard-copy maps. GPS photographs were renamed using the same identification numbers and are linked to a GIS data layer.

## RESULTS

This survey documented shoreline conditions at 295 parcels on Six Mile Lake. Approximately 77% (227) of shoreline properties on Six Mile Lake were considered to be developed.

Habitat generally considered suitable for *Cladophora* growth was present along at least part of the shoreline of 134 properties (45%). Noticeable growths of *Cladophora* or other filamentous green algae were found along the shoreline at 29 parcels (10% of the total or 22% of properties with suitable habitat). At properties where *Cladophora* growth was observed, nearly 50% consisted of light or very light growth, whereas only 7 parcels had growth in the moderate-heavy to heavy categories (Table 4).

**Table 4.** *Cladophora* density results.

<b><i>Cladophora</i> Density</b>	<b>Parcels</b>	<b>Percent</b>
Very light	4	1%
Light	10	3%
Light to Moderate	2	1%
Moderate	6	2%
Moderate to Heavy	2	1%
Heavy	2	1%
Very Heavy	3	1%
TOTAL	29	10%

A few areas of moderate to heavy *Cladophora* growth were documented along the western shoreline of Six Mile Lake (Figure 4). None of these growths occurred adjacent to tributary streams.




Figure 4. *Cladophora* algae density results for Six Mile Lake.

Greenbelt scores ranged from 0 (little to no greenbelt) to 7 (exemplary greenbelt). Less than half of greenbelts (41%) along the Six Mile Lake shoreline were found to be in good or excellent condition (Table 5). An equal number of parcels (41%) received a greenbelt rating in the poor or very poor categories.

**Table 5.** Greenbelt rating results.

<b>Greenbelt Rating</b>		<b>Number of Parcels</b>	<b>Percent of Parcels</b>
0	Very Poor (absent)	72	24%
1-2	Poor	50	17%
3-4	Moderate	52	18%
5-6	Good	39	13%
7	Excellent	82	28%

Greenbelt status ranged, in general, from high quality in the northern portions of Six Mile Lake to poor in the central and southwestern portions of Six Mile Lake (Figure 5). Although clusters of properties with poor greenbelts occurred throughout the lake, they are more prevalent along the western shoreline.




Figure 5. Greenbelt score totals results for Six Mile Lake.

Some form of shoreline alteration was noted at 37% of shoreline properties (Table 6). The majority of alterations consisted of riprap (15%), while seawalls (wooden, concrete, or metal), account for approximately 7% of altered shorelines.

**Table 6.** Shoreline alteration results.

<b>Alteration Type</b>	<b>Number of Parcels*</b>	<b>Percent of Parcels With Alteration*</b>
Riprap (small)	43	15%
Riprap (boulder)	27	9%
Seawalls	20	7%
Beach Sand	28	9%
Unaltered	185	63%

*\*Numbers and percentages quantify alteration type, many parcels had multiple alterations*

Erosion was noted at 108 parcels (36%) on the Six Mile Lake shoreline (Table 7). 24% of shoreline properties with erosion were classified as minor in terms of severity, while roughly 1% of properties were considered severe.

**Table 7.** Shoreline erosion results.

<b>Erosion Category</b>	<b>Number of Properties</b>	<b>Percent of Properties*</b>
Minor	71	24%
Moderate	33	11%
Severe	4	1%
TOTAL	108	36%




Figure 6. Shoreline erosion severity results for Six Mile Lake.

## DISCUSSION

In general, development of shoreline parcels can negatively impact a lake's water quality due to a multitude of factors. Among the most serious impacts are: 1) loss of vegetation that would otherwise absorb and filter pollutants in stormwater runoff as well as stabilize shoreline areas and prevent erosion, 2) increased impervious surface area such as roofs, driveways and roads, which leads to greater inputs of stormwater runoff and associated pollutants, and 3) waste and byproducts of human activity such as septic leachate, fertilizers and decomposing yard waste that potentially reach and contaminate the lake water. Clearly, there are many problems associated with development, but there are also many solutions for reducing or even entirely eliminating impacts.

Numerous best management practices have been developed that help minimize negative impacts to water quality and which can be utilized during, or retroactively after, the development of shoreline parcels. A buffer of diverse, native plants can be maintained along the shoreline to filter pollutants and reduce erosion. Impacts from stormwater generated from roofs, roads, and driveways can be reduced using rain barrels, rain gardens, grassy swales, and many other techniques. Leachate reaching the lake from septic systems can be minimized by pumping the septic tank regularly, having all components of the septic system inspected regularly and replacing the septic system when necessary. Mulch can be composted far from the shoreline and fertilizers applied sparingly, if at all.

Results from the 2016 shoreline survey indicate that some of the aforementioned issues may pose a threat to the water quality and overall health of Six Mile Lake. Widespread removal of shoreline vegetation is the paramount concern. Just under half (41)% of all shorelines exhibited greenbelts that were in poor condition. Erosion is also a concern, with light to moderate erosion commonly occurring throughout the same areas most heavily impacted by vegetation removal. Algal indicators of nutrient pollution are far less extensive than the above issues.

Comparisons with prior shoreline surveys show changes in these measurements over time. The total number of properties with documented *Cladophora* growth decreased by 4% since 2008 (Table 8). This indicates that the trend of increasing near-shore nutrient pollution, identified in the 2008 report, is abating. Outreach regarding septic system maintenance, phasing out of old systems, and properly siting new systems may be playing a role in reduction in nutrient pollution related to septic systems. A few problem areas still exist (as evidenced by heavy *Cladophora* growth occurring along the shoreline of five parcels), which warrant further investigation. Where human-caused nutrient pollution is occurring, the source has to be identified in order to address the problem. Although impeded by factors such as wind, wave action, currents, and groundwater paths, efforts by trained personnel to identify specific nutrient input sources on individual properties are often successful.

**Table 8.** Critical shoreline survey parameter comparisons: 2000 to 2016.

<b>Survey Parameter</b>	<b>2000 Survey Results</b>		<b>2008 Survey Results</b>		<b>2016 Survey Results</b>	
	Properties	%	Properties	%	Properties	%
<i>Cladophora</i> Algae Presence	23	8%	40	14%	29	10%
Poor Greenbelts (score 0-2)	67	23%	100	34%	121	41%
Erosion	3	1%	32	11%	108	37%
Shoreline Alterations	ND	ND	89	30%	110	37%

Average greenbelt conditions are worsening throughout much of the Lake. The lack of vegetation on the Lake’s shoreline, which provides habitat and acts as a food source, can impact the abundance and diversity of aquatic organisms, ranging from minute crustaceans to top tier predator fish. Furthermore, the absence of vegetation leads to greater amounts of shoreline erosion and less filtration of pollutants. Shoreline survey data supports this relationship, with increases in erosion documented in tandem with declining greenbelt quality over the past 16 years. Although a substantial number of greenbelts are in poor condition, 28% of properties received a perfect score, indicating exemplary greenbelt health. Properties with healthy, intact greenbelts provide a model for improvement for other shoreline properties.

Compared to other lakes in the region, Six Mile Lake has a relatively low number of parcels exhibiting *Cladophora* growth (Table 9). This is due, at least in part, to a lack of suitable substrate for *Cladophora* growth. Results from this survey indicate that just over half (55%) of all properties lack habitat suitable for *Cladophora* growth. Suitable habitats include hard surfaces such as rocks, boulders, riprap, submerged wood, and metal seawalls. This limits the usefulness of *Cladophora* as an indicator of nutrient pollution. With no supporting habitat for *Cladophora*, it is difficult to make assertions about the level of nutrient pollution occurring along certain stretches of Six Mile Lake's shoreline using the methods at hand.

**Table 9.** Shore survey statistics from Northern Michigan lakes.

Lake Name	Survey Date	<i>Cladophora</i> *	Heavy Algae*	Erosion*	Poor Greenbelts*	Alterations*
Beals Lake	2016	0%	0%	0%	17%	0%
Ben-Way Lake	2016	3%	0%	84%	47%	40%
Burt Lake	2009	47%	29%	4%	36%	46%
Bellaire Lake	2017	35%	1%	27%	30%	55%
Charlevoix, Lake	2012	22%	19%	14%	34%	79%
Clam Lake	2017	48%	5%	30%	51%	55%
Crooked Lake	2012	29%	26%	14%	51%	65%
Douglas Lake	2015	27%	6%	17%	53%	60%
Elk Lake	2017	84%	2%	52%	30%	87%
Ellsworth Lake	2016	40%	14%	38%	24%	23%
Hanley Lake	2016	11%	0%	33%	19%	23%
Huffman Lake	2015	14%	0%	7%	57%	70%
Huron, Duncan Bay	2013	41%	2%	19%	45%	63%
Huron, Grass Bay	2013	0%	0%	4%	0%	8%
Intermediate Lake	2016	19%	9%	53%	63%	77%
Lance Lake	2014	19%	0%	12%	35%	31%
Larks Lake	2006	4%	0%	ND	12%	29%
Mullett Lake	2016	44%	6%	36%	59%	76%
Pickerel Lake	2012	27%	33%	15%	52%	64%
Round Lake	2014	21%	0%	27%	44%	44%
Scotts Lake	2016	0%	0%	2%	18%	7%
Silver Lake	2014	3%	0%	70%	53%	65%
Skegemog Lake	2017	52%	5%	40%	46%	76%
St. Clair Lake	2016	4%	0%	13%	34%	21%
Six Mile Lake	2016	10%	24%	13%	41%	37%
Thayer Lake	2017	11%	1%	32%	16%	22%
Thumb Lake	2007	4%	0%	ND	ND	39%
Torch Lake	2017	39%	5%	26%	20%	ND
Walloon Lake	2016	62%	2%	17%	39%	80%
Wildwood Lake	2014	5%	0%	22%	45%	50%
Wilson	2016	27%	5%	29%	11%	14%
AVERAGE	NA	24%	6%	26%	36%	47%

*\*Percentages are in relation to number of parcels on the lake shore, except for “heavy algae”, which is the percent of only parcels that had Cladophora growth. Erosion is the percentage of parcels with moderate to severe erosion and poor greenbelts include those in the poor or very poor categories. ND=no data.*

Although many properties on Six Mile Lake are experiencing some form of erosion, the majority (66% of all erosion sites) are considered minor and only 1% of all erosion is considered to be severe. Many properties with patches of lawn at water's edge experience a minor undercutting caused by waves and ice shove. Properties with artificial beach sand usually experience some loss of sand into the lake, evidenced by small erosional rills leading into the lake. Although not catastrophic, these types of minor erosion do have the ability to degrade the water and habitat quality of Six Mile Lake. In addition, the wake from large boats may be exacerbating erosion as unnaturally large waves break along the shoreline.

Small lakes have less water surface width for wind to generate waves (fetch), resulting in smaller naturally occurring waves and less regular impact to the shoreline from wave energy. Likewise, winter ice-shove is also less impactful on smaller lakes. Without exposure to erosional forces commonly found on larger lakes, shorelines generally retain more vegetation and require less armoring. This is likely why Six Mile Lake ranks amongst the lowest for percentage of shoreline properties with alterations when compared to other Northern Michigan lakes surveyed under the same protocol (Table 9). Furthermore, repair of the current erosion sites should be relatively easy to accomplish with plantings, as the low-energy shoreline allows for establishment of new plants.

Water clarity actually appears to be increasing in Six Mile Lake, which may be the result of a decrease in the amount of algae in the water column (Tip of the Mitt Watershed Council 2017). The amount of algae is influenced, among other things, by the availability of nutrients and therefore, a reduction in algae indicates a possible reduction in nutrients. Zebra mussels also filter-feed algae from the water column, thereby reducing algae and phosphorus concentrations. While these data suggest a decrease in nutrient pollution, there are numerous factors to consider when interpreting such data. One is that all water quality data referenced above have been collected in open water, far removed from shoreline areas.

To prevent changes to the lake ecosystem, changes need to be made in shoreline property management. Mismanagement of shoreline properties can degrade the lake's water quality, diminish fisheries, and even create an environment that poses threats to human health.

## RECOMMENDATIONS

The full value of a shoreline survey is only achieved when the information is used to educate riparian property owners about preserving water quality, and to help them rectify any problem situations. The following are recommended follow-up actions:

1. Keep the specific results of the survey confidential (e.g., do not publish a list of sites where *Cladophora* algae were found) as some property owners may be sensitive to publicizing information regarding their property.
2. Send a general summary of the survey results to all shoreline residents, along with a packet of informational brochures produced by the Watershed Council and other organizations to provide information about threats to the Lake's ecosystem and public health as a result of poor shoreline property management practices as well as practical, feasible, and effective actions to protect water quality.
3. Organize and sponsor an informational session to present findings of the survey to shoreline residents and provide ideas and options for improving shoreline management practices that would help protect and improve the Lake's water quality.
4. Inform owners of properties with heavy *Cladophora* growths of specific results for their property, ask them to fill out a questionnaire in an attempt to interpret causes of the growth, and offer individualized recommendations for water quality protection.

Following the questionnaire survey, property owners have the option to have the Watershed Council perform site visits and conduct groundwater testing in an effort to gain more insight into the nature of the findings. Again, it should be stressed that all information regarding names, specific locations, and findings be kept confidential to

encourage property owner participation in this project.

5. Inform owners of properties with poor greenbelt scores and those with severely eroded shorelines of specific results for their property. Supply these property owners with information (e.g., brochures) regarding the benefits of greenbelts and/or the problems associated with erosion. Encourage property owners to improve greenbelts using a mix of native plants and to correct erosion problems. Property owners can have the Watershed Council perform site assessments and carry out projects to improve greenbelts and/or correct erosion problems.
6. Utilize the Internet and other organizations' websites to share survey information. A general summary report and this detailed report can be posted websites because they do not contain any property-specific information. Property-specific information can be shared by randomizing and encrypting the shoreline survey database and providing property owners with a code number that refers specifically to survey results from their property. The Watershed Council is available to assist with this approach.
7. Continue to support the Tip of the Mitt Watershed Council Volunteer Lake and Stream Monitoring programs by providing volunteer support. The information collected by volunteers is extremely valuable for evaluating water quality and determining trends. Six Mile Lake Association is encouraged to continue supplying volunteer help and volunteers should attend training sessions held by the Watershed Council to ensure that a complete set of quality data is being collected each year.
8. Repeat some version of the survey periodically (ideally every 5 - 10 years), coupled with the follow-up activities described previously, in order to promote water quality awareness and good management practices on an ongoing basis. During each subsequent survey, more details about shoreline features are added to the database, which can be utilized for other water resource management applications.

## LITERATURE AND DATA REFERENCED

Charlevoix County GIS Office. 2004. Charlevoix County Digital Orthophotography. Charlevoix, MI. <http://www.charlevoixcounty.org/>

Charlevoix County GIS Office . 2014. Charlevoix County GIS Parcel Data. Charlevoix, MI. <http://www.charlevoixcounty.org/>

Antrim County Equalization/GIS. 2015. Antrim County GIS Parcel Data. Bellaire, MI. <http://www.emmetcounty.org/>

National Oceanic and Atmospheric Administration (NOAA). 2003. Coastal Great Lakes Land Cover Project. NOAA Coastal Services Center. Charleston, SC. <http://www.csc.noaa.gov/crs/lca/greatlakes.html>

Michigan Department of Natural Resources. 2008. Lake Maps by County. Lansing, MI. [http://www.michigan.gov/cgi/0,1607,7-153-30301\\_31431\\_32340---,00.html](http://www.michigan.gov/cgi/0,1607,7-153-30301_31431_32340---,00.html)

National Oceanic and Atmospheric Administration (NOAA). 2011. Coastal Great Lakes Land Cover Project. NOAA Coastal Services Center. Charleston, SC. <http://www.csc.noaa.gov/crs/lca/greatlakes.html>

Tip of the Mitt Watershed Council. 2016. Comprehensive Water Quality Monitoring Program Data. Tip of the Mitt Watershed Council. Petoskey, MI. <http://www.watershedcouncil.org/Protect/>

Tip of the Mitt Watershed Council. 2016. Volunteer Lake Monitoring Program Data. Tip of the Mitt Watershed Council. Petoskey, MI. <http://www.watershedcouncil.org/Protect/>

Tip of the Mitt Watershed Council. 2001. A Shoreline Survey of Six Mile Lake. Tip of the Mitt Watershed Council. Petoskey, MI. <http://www.watershedcouncil.org/>

Tip of the Mitt Watershed Council. 2009. A Shoreline Survey of Six Mile Lake. Tip of the Mitt Watershed Council. Petoskey, MI. <http://www.watershedcouncil.org/>